29-686



Subaru steering wheel control interface

Supported functions

Volume up Volume down Seek/track up Seek/track down Source Phone



Connection instructions

Connect the head unit specific patch lead to the interface first. If using a universal patch lead, check it is setup correctly. Refer to the diagrams overleaf to check the patch lead is correct.

Connect the ISO connectors and patch lead to the new head unit.

Connect the 29-686 harness to the vehicle harness.

Test the steering controls.

Fit the head unit into place and test the steering controls again.

Notes

29-686



Subaru steering wheel control interface

Supported functions

Volume up
Volume down
Seek/track up
Seek/track down
Source
Phone



Connection instructions

Connect the head unit specific patch lead to the interface first. If using a universal patch lead, check it is setup correctly. Refer to the diagrams overleaf to check the patch lead is correct.

Connect the ISO connectors and patch lead to the new head unit.

Connect the 29-686 harness to the vehicle harness.

Test the steering controls.

Fit the head unit into place and test the steering controls again.

Notes

In Car Technologies

01392 829435

In Car Technologies

01392 829435

Patch lead wiring configurations



29-000 Self learning units Single wires pins 1 and 2 No loops

29-001 Alpine

3.5 jack pins 1, 2 and 3 Loop pins 9 + 10

29-004 JVC Single wire pin 3, 3.5 jack pins 2 and 3 Loop pins 11 + 12

29-007 Pioneer 3.5 jack pins 1, 2 and 3 Loop 5 + 6 (some leads also have 7+8 looped, both are the same)

29-011 Zenec Single wire pin 3 Loops 5 + 6, 7 + 8 and 9 + 10

Troubleshooting

Radio not turning on

Check there is an ignition power supply to the new head unit and the interface.

Steering controls not working

Check the patch lead is correct and was connected to the interface before the interface was connected to the vehicle.

Reset the interface by completely disconnecting, wait for 2 minutes, then reconnect.

Check the purple wire is connected to a good ground.

Check the wires in the harness are matching wires in the car, the white wire from the interface is for the steering control signal.

Check the interface has software version VX01 V2.38 or newer.



29-003 Clarion 3.5 jack pins 2 and 3 Loops 5 + 6 and 11 + 12

29-005 Kenwood Single wire pin 3 Loop pins 7 + 8

29-008 Sony 3.5 jack pins 1, 2 and 3 Loops 7 +8 and 9 + 10


29-012 Philips Single wire pin 3 Loops 5 + 6, 9 + 10 and 11 + 12

Patch lead wiring configurations



Single wires pins 1 and 2 No loops

29-000 Self learning units



3.5 jack pins 1, 2 and 3

29-004 JVC Single wire pin 3, 3.5 jack pins 2 and 3 Loop pins 11 + 12

29-007 Pioneer 3.5 jack pins 1, 2 and 3 Loop 5 + 6 (some leads also have 7+8 looped, both are the same)

29-011 Zenec Single wire pin 3 Loops 5 + 6, 7 + 8 and 9 + 10

Troubleshooting

Radio not turning on

Check there is an ignition power supply to the new head unit and the interface.

Steering controls not working

Check the patch lead is correct and was connected to the interface before the interface was connected to the vehicle.

Reset the interface by completely disconnecting, wait for 2 minutes, then reconnect. Check the purple wire is connected to a good ground.

Check the wires in the harness are matching wires in the car, the white wire from the interface is for the steering control signal.

Check the interface has software version VX01 V2.38 or newer.





3.5 jack pins 2 and 3 Loops 5 + 6 and 11 + 12

29-005 Kenwood

Single wire pin 3

Loop pins 7 + 8

29-008 Sony

3.5 jack pins 1, 2 and 3

Loops 7 +8 and 9 + 10

29-012 Philips Single wire pin 3 Loops 5 + 6, 9 + 10 and 11 + 12