

Road Angel and Grundig sets not working with steering wheel controls



Since late 2021 a number of double DIN radios have appeared on the market with older known brands names attached to them. The two most prominent are Road Angel and Grundig.

These sets use resistive learning for steering wheel controls, like most other Chinese built radios.

On most of these sets and with most cars the patch leads for resistive learning, either through SWC/KEY wires or a 3.5mm jack work correctly.

SWC interface type	2 wire patch lead	3.5mm jack patch lead
29 Series	29-000	29-016
29-UC-050 Series	29-UCCAB-000	29-UCCAB-016
29-CT Series	29-CT-025	29-CT-025
39 Series	39-HU-UNI	Not Compatible
49 Series	49-000	Not Compatible

ON SOME CARS IT IS NOT POSSIBLE TO RETAIN STEERING WHEEL CONTROLS WITH THESE SETS.

We have seen instances on some cars where it is not currently possible to retain the steering wheel controls when using these sets and no inputs are recognised. We currently do not have a solution for fixing this issue or a list of cars that are affected by this. The only solution we can currently offer is to use a different radio from a more well-known brand such a Pioneer, Sony, Kenwood or Alpine.